
US ERA ARCHIVE DOCUMENT

## Situation Photo Log

Monday, June 18, 2012 Kalamazoo River / Enbridge Spill

## Weather / River Conditions for Monday (6-18-2012)

Conditions: Late Moring Rain / Sunny Afternoon Ambient Air Temperature High: 93° F Average River Water Temperature: 72.79° F Average River Sediment Temperature: 68.71° F



Prepared by: Matthew Haak START-USEPA Situation Unit Leader




1. Ceresco Dam upstream portage observed being constructed.



2. Ceresco Dam upstream portage observed being constructed.



3. Ceresco Dam boom, observed crews removing debris.



4. Ceresco Dam sheen observed.




5. Ceresco Dam sheen observed.



6. Ceresco Dam sheen observed.



7. Ceresco Dam rainbow sheen observed on downstream side of boom.



8. Ceresco Dam sheen observed bubbling up and going over dam.



9. Ceresco Dam sheen observed.



10. Ceresco Dam buoys deployed.



11. Ceresco Dam sheen observed.



12. Ceresco Dam sheen observed.



13. CO.4 Boat launch sheen observed after boat launched.



14. MP5.6 LDB sheen observed.




15. MP5.63 LDB vegetation accumulating.



16. Observed well installation below Ceresco Dam.



17. MP29.25 Poling crew observed.



18. MP30.0 LDB observed crew performing ring test.



19. MP30.0 LDB observed crew performing ring test.



20. MP30.0 LDB observed crew performing ring test.



21. MP30.0 LDB sheen observed around boat when we docked.



22. MP30.0 LDB sheen observed around boat when we docked.




23. MP30.8 LDB sheen observed.



24. MP30.8 LDB sheen observed.



25. MP32.5 STRIKE poiling team observed.



26. MP32.5 RDB sheen observed around boat when we reversed.



27. MP32.5 RDB sheen observed around boat when we reversed.



28. MP34.0 STRIKE poiling team.



29. MP36.25 RDB overbank STRIKE team observed.



30. Morrow Lake Delta buoys deployed.



31. Morrow Lake Delta buoys being deployed.



32. Morrow Lake Delta poling crew observed.




33. Morrow Lake Delta sheen sweep observed at E4 boom.



34. Morrow Lake poling crew observed.



35. MP33.0 observed crew decontaminating test ring.



36. MP29.0 poling crew observed.